January 5, 2010 8:29:03 AM

Item ID:

D205-564-011

Accept



Setup Start



Revision ID:

Start Date:

Bearpaw Item Name:

Require Date: 18/01/2010

05/01/2010

Start Qty: 10.00 Req'd Qty: 10.00

Cust Item ID:

Customer:

Stop

Referen ::

Process Plan:

Date/0-1-05 Tooling:

Date:

Run

Start



Approvals: QC:

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID** Operation Description Set Up/ **Run Hours**

Draw Number Draw Rev.

Plan Code

Accept Qty Qty

Reject Reject Number Stamp

Insp.

Draw Nbr

Revision Nbr

D2521

Rev J

100

DC

Document Control

DOCUMENT CONTROL

Memo

0.00

0.00

Photocopy blue file and type labels per PPP D205-564-011 CHG008

151

Packaging Packaging

Pick Kit

0.00

Memo

OC4-100% Inspect kits for completeness

0.00

fu 10/0/29 (1)

160

Memo

0.00

0.00

Quality Control

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector				
									,				
									,				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:					
		esolution:											
NCR:		\	WORK ORDE	R NON-CONFORMA	NCE (NC	R)							
		Description of NC	Corrective Action Se		on B	Verific	eation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Section		Chief Eng	Approval QC Inspector				

Work Order ID 54891

January 5, 2010 8:29:03 AM

Item ID:

D205-564-011

Item Name. Bearpaw

Start Date: Require Date: 18/01/2010

05/01/2010

Start Qty: 10.00 Req'd Qty: 10.00



Accept



Cust Item ID:

Customer:

Reference:

Revision ID:

Approvals:

Date:

SPC (Y/N):

Tooling:

Date:

Date:

Start Run

Setup Start

Stop



Sequence ID/ **Work Center ID**

170



Packaging

Operation Description

Identify as per dwg & Stock Location:

Date:

Memo

Set Up/ **Run Hours**

0.00

0.00

Draw Number

Draw Rev.

Plan Code Accept

Reject Qty

Reject Insp. Number

Stamp

Packaging

180

QC

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10 103/02 Af

Quality Control

W/O:

W/O:		WORK ORDER	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _						

Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section E	}	Verification	Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC Inspecto			
						!					
			·	7							
						·		:			
				1/M/H/J							
	ate & initial										

/ b- ,	January 5, 2010 8:29:0	09 AM												Page 1
	Work Order ID: 54891 Farent Item: D205-564-011 Parent Item Name: Bearpaw Comments:									art Date: 05/6 Start Qty: 10.0		Required Date: 18/01/2010 Required Qty: 10.00		
	Composite Item ID/	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location) wast Speation	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued		Date Issued	Status
\ 'x1C	D2521 4	···	Manufactured	No			151	Each	0.0000	20.0000	B 574	f 9	2 2	, b
χID	D2182B & Q 5 5'		Manufactured	No			151	f	323.0160	37.0000			h	
	Rabber Cusmon				Wareho		Loc	<u>Oty</u>	Loc Code					
						<u>ation</u>								
					Main W	arehouse	_							
					ST		25	9.886		_		-		
						28042		7.33 0.33		-		_		
						30872 45405	2:	0.33 2.226		-		-		
					Main W	arehouse				•		-		
					ST4		2	93.13		**		_		
						52649	2	93.13			52649	• -		
ر 1 ₄ را	D2274 John J. J. Radius Block		Manufactured	No			151	Each	41.0000	200.0000	B554	143	/1	14/4/28 (10)
·	Radius Dioek				W'areho	ouse	<u>Loc</u>	Qty	Loc Code					
					Loc	ation								
					Main W	arehouse								
					ST			41		-	····	_		
						52644		41				_		-

										, i
W/O:			WORK ORDER CHANGES							
DATE	STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
-		,		•						
	}			·						
Part No):		PAR #:	Fault Category:	NCI	R: Yes	No DG	A:	Date: _	
	R	esolution:		Disposition:	QA	N/C C	closed:		Date: _	
[MORK OPDED NON COM	IEODMANCE	: /N/C	D/			· · · · · · · · · · · · · · · · · · ·

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	3	Verification	Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C					
								· •			



Loc Code Warehouse Loc Qty Location

7

7

50007 110

Main Warehouse ST 46651

W/O:		We C	WORK ORDER CHANGES									
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								<u> </u>				
Part No	:	PAR #:	Fault Category:	NCR: Y	es No DC	A:	Date: _					
	Re	solution:	Disposition:	QA: N/	C Closed:		Date: _					
NCR:			WORK ORDER NON-CON	IFORMANCE (N	ICR)			<u> </u>				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	T	Description of NC	Corrective Action Section B				Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC inspector			
		,									

January 5, 2010 8:29:09 AM

Work Order ID: 54891

Parent Item:

D205-564-011

Parent Item Name: Bearpaw

Comments:

Component tem	ID/
Item Name	

Replacement Mfg/ Purch Item ID

Bolt

Start Date: 05/01/2010

Start Qty: 10.00

Required Date: 18/01/2010

Required Qty: 10.00

Primary Item Location

Warehouse

No

Lister Lesition

Route Seq ID

151

Unit of Measure

Each

Each

Loc Oty

Oty on Hand

Loc Code

Remaining Qty To Pick

Issued

m1/3355

Date
Issued Status

649.0000 80.0000

	. 0
AN4-15A	20 Y
1 24 A 24 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

Purchased

Purchased

No

Location Main Warehouse ST 649 649 113359 0 17406 0 51764

151

456.0000 200.0000

/c/0/01/27 (10)

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	456	
113121	56	
113538	400	

M1/3538

HO Boll

HD

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
							-						
Part No	:	PAR #:	Fault Categ	jory:	NCR:	Yes N	lo DQ	4 :	_ Date: _				
Re		esolution:	Disposition):	QA: N	/C Clo	sed:		Date: _				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)							
DATE	CTED	Description of NC	Corrective Action		Section B		Verific	ration	Approval Chief Eng	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		Section C			QC Inspector			
	1	1	1 1	•	1		1			1			

ST 4161 102552 6 104248 110507 184 2965 111827 1000 113422 15924

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE	0755	Description of NC	!	Corrective Action Section B	• • • • • • • • • • • • • • • • • • • •	Verification	Approval	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng				
						:					
						``					




DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECK	APPROVED	DRAWING NO. REV. D2521 SHEET 1 OF	
DATE	The second secon	TITLE SCAL	_E
	06.07.28	205 BEARPAW NT	s
Α	95.11.28	NEW ISSUE	
В	96.01.11	SHOW BENDING MOVE HOLES	
С	96.01.29	ADJUST HOLE LOCATION FOR TOOLING	
D	96.05.14	ADJUSTED BEAR PAW THICKNESS	
E	96.12.18	43.500 WAS 46.750	-
F	97.05.07	ADDED REAR POCKET, MOVED HOLES	
G	98.08.06	ADD C'BORE AND CHAMFER EDGES	-
H	03.01.30	CHANGE GEOMETRY FOR RUN-ON LDG.	
I	05.05.20	REMOVE BEND; CHANGE TOLERANCES	
J	06.07.28	CHANGE FOR FLOAT SKIDTUBE	

SHOP COPY RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

	Johnson.								•
W/O:			WO	RK ORDER CHANGES					
DATE	STEP	PR	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•		· .					
7.0548.0									
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	:	_ Date: _	
	Res	solution:	Disposition	ı:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			
DATE	CTED	Description of NC Section A	Corrective Action Section B			Verification	ation	Approval	Approval
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio		Chief Eng	QC Inspector







NOTES:

- 1) MATERIAL: UHMW BLACK PER SPEC CONTROL DRAWING D2689, 1.000 THICK (MACHINE TO 0.950)
- 2) FINISH: NONE
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.030
- 6) PART IS SYMMETRIC ABOUT &


COPYRIGHT @ 1995 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


W/O:			WO	RK ORDER CHANGI	ES					
DATE	STEP	PRO	OCEDURE CHAN	IGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·						
Part No: PA		PAR #:	Fault Categ	ory:	NCR:	Yes N	lo DQ	A:	Date:	
	Resolution:									
NCR:			WORK ORDE	R NON-CONFORMA	NCE (I	NCR)				
		Description of NC Section A	Corrective Action Section				Verific	ation	Approval	Approval
DATE	STEP		Initial Chief Eng	Action Description Chief Eng		ign & Date	Verification Section C		Chief Eng	QC Inspecto
					•					
										;
1	1	1	1		1		1		1	ī





DART AEROSPACE LTD DESIGN DRAWN BY CB HAWKESBURY, ONTARIO, CANADA APPROVED DRAWING NO. REV. J CHECKED D2521 SHEET 3 OF 3 TITLE DATE SCALE 1:4 205 BEARPAW 06.07.28



SECTION A-A







THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD

W/O:		•	WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				1.34						
			*	90 T T T T T T T T T T T T T T T T T T T						
									. 44	
Part No):		PAR #:	Fault Category:	NCF	R: Yes	No DQ	A:	_ Date: _	1
	Re	esolution:		Disposition:	ΟΔ-	N/C C	losed:		Date:	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NČ		Corrective Action Section B			Annessal	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
		8. 3								
¥										

REFERENCE ONLY

5.0 PARTS LIST

Qty	Part Number	Description	
Х	D205-564-011	BEARPAW INSTALLATION	
´ 8	D2182B0551	RUBBER CUSHION	
20	D2274/	RADIUS BLOCK	
2	D2521	BEARPAW	
20	D2529	WASHER	
. 8	D2947 >	CLAMP	
c. 4 :	D3544-041	CLAMP	
′ 8	AN4-13A >	BOLT	
20	AN4-15A	BOLT	
20	AN960JD416	WASHERS	
20	MS21042L4	NUT (OR MS21042-4)	

Qty	Part Number	Description
Х	DSI-9328-011	RUN-ON LANDING WEARPLATE KIT
2	D3511-041	WEARPLATE
16	AN4-17A	BOLT
4	AN4-11A	BOLT
4	AN970-4	WASHER
16	MS21042L4	NUT (OR MS21042-4)

Dart Aerospac	ce Ltd
---------------	--------

	•								•
W/O:			W	ORK ORDER CHANG	GES			÷ •	, ,
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,								
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	\ :	_ Date: _	
				Disposition: QA: N/C Closed: Date:					
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC	Description of NC Corrective Action			Verific	erification Approx		Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
					•				
		,							
									}